


VDO Tachometer Lamp Replacement Instructions

Page 1 of 1

Date Originated: 05/12/06	Revision: A	Revision Date:	Standards No.	5000041-XX
Subject: VDO Programmable	Tachometer Lam	p Replacement Instructions		

Replacing the Wedge Lamp

- 1. Turn and pull lamp socket to remove it from gauge housing. This may require the use of pliers (see diagram).
- 2. Pull wedge lamp straight out to remove it from socket.
- 3. Replace with new lamp.
- 4. Press lamp socket straight into gauge housing until it snaps into place.



Gauge Lamp Accessory Kits

Description	Voltage	VDO Part No.	IC Kit No.	
2 Wedge Lamps	12V	600 815	4050352	
2 Wedge Lamps	24V	600 826	4050353	
2 Lamp Sockets	-	600 840	4050354	