

Eaton Electric Shift Units (Parts-Pre 1986)

Internal Spring

Eaton Part #32605

Internal Spring & Lever Assembly (Includes 32605)

Eaton Part #32772

Drive Screw Assembly (Includes 32369 Bumper, V1762)

Eaton Part #32364

Electric Shift Repair Parts

Part Number	Quantity	Description
V1568 / K1006	1	Motor
V1656	1	Limit Switch
V1705	1	Motor Gasket
V1706	1	Cover Gasket
V1707	1	Bearing Cover
V1761	1	Bearing
V1795	2	Bushing
V1796	1	Insulator