



<b>TECHNICAL BULLETIN No. 0107</b>	<b>71441-30 Discharge Fitting (Replacement of 71441-22)</b>
--	---

Effective on orders received beginning February 1, 2010, 71441-22 discharge fitting will be replaced by the 71441-30 discharge fitting. Existing open orders will not be affected.

## REPLACEMENT FITTING

**Waterous will no longer offer fitting 71441-22. Discharge Fitting 71441-30 replaces 71441-22 (see A-1173 for dimensional differences).**

Features of the fitting are described below:

- **4-Bolt Flange vs. 2-1/2" NPT Port:** 71441-30 discharge fitting is equipped with a 4-bolt flange on top of the fitting versus a 2-1/2" NPT Port on 71441-22 discharge fitting.

**NOTE:** The addition of an auxiliary blind flange or tapped flange for the top port of the fitting will not be supplied unless specified.

*NOTE: The information in this technical bulletin was current at the time of printing. Waterous reserves the right to change this information.*