

Contact Waterous for more information (651) 450-5234, option 3

## Technical Bulletin No. 135

## Updates to CP-Series Pump Documentation

Date: March 24, 2020 Effective: Immediately

Review the following notice addressing changes to the listed document:

## F-1031-3064—CP-5 Installation Instruction

- · Updates to admonition formatting.
- Added a note to clarify instructions on eliminating air entrapment in the plumbing.
- Update to recommended oil-hose size.